

Rigid Part Recognition Problem

Why is the proposed method suitable for an estimated 50% of manufactured flat parts?

Because most parts will have a few simple features like straight edges or circular holes. These are required for attaching the part to a larger assembly. With a small number (*e.g.* 2-3) of these features, we could recognise and estimate the pose of the parts.