Key Principal Component Modes for TEE?

What do the first few principal components encode for the TEE dataset?

Looking at the figure, we might see variation in:

Column Effect

- 1 width of the tee head?
- 2 overall size of part?
- 3 thickness of the tee head?
- 4 thickness of tee stem?

However, these variations are learned empirically, so often are not tidy (as can be seen here).